



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
**Date:** August 3, 2009

Reviewed: LR

<b>Mine Name:</b> High Country Rock	<b>Permit Number:</b> S/051/0011
<b>Operator Name:</b> High Country Rock Company LLC	<b>Inspection Date:</b> July 29, 2009
<b>Inspector(s):</b> L Heppler	<b>Time:</b> 7:00 PM
<b>Other Participants:</b> none	<b>Mine Status:</b> ACT

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Renewal Date:** 03-17-2010 **Bond Amount:** \$7,000 **Permit fee** is delinquent - \$150

**Purpose of Inspection:** Routine annual Inspection. This site was last inspected as a small mine site on 09/17/2008

**Inspection Summary:** No concurrent reclamation was evident. No evidence of growth medium salvage or any revegetation efforts. Topsoil is extremely limited or non existent, but adjacent land does support a sparse vegetative community. Every effort should be made to growth medium from the site. No trash was noticed on site.

Photos were taken to document site conditions, see attached photos.

**Conclusions and Recommendations:** Permit is considered suspended until Annual Permit fee is paid. OGM to continue annual inspections and monitor the site when in the area.

**Inspector's Signature**

LAH:vs

cc: Gary Applegate

O:\M051-Wasatch\S0510011-HighCountryRock\inspections\Insp-07292009.doc

